



**EMSL Analytical, Inc.**

200 Route 130 North, Cinnaminson, NJ 08077  
Phone/Fax: (800) 220-3675 / (856) 786-5974  
<http://www.EMSL.com> [cinnaslab@EMSL.com](mailto:cinnaslab@EMSL.com)

EMSL Order: 041602195  
CustomerID: SSHM25  
CustomerPO: CC-016879  
ProjectID:

Attn: **Thomas Kelting**  
**Sunshine Home Inspection, LLC**  
**1228 Pine St.**  
**New Orleans, LA 70118**

Phone: (504) 248-8798  
Fax:  
Received: 01/30/16 10:30 AM  
Analysis Date: 2/1/2016  
Collected: 1/27/2016

Project: 1819E

**Test Report: Asbestos Analysis of Dust Samples Using Method ASTM 6480**

SAMPLE ID	AREA SAMPLED (cm <sup>2</sup> )	ASBESTOS TYPE	ASBESTOS STRUCTURES	Sensitivity (str/cm <sup>2</sup> )	CONCENTRATION (str/cm <sup>2</sup> )	COMMENTS
1 041602195-0001	929.03	Chrysotile	142	1440	204000	Due to excessive particulate the analytical sensitivity of 260 str/cm <sup>2</sup> as required by the method was not reached.

Analyst(s)

William Nguyen (1)

Benjamin Ellis, Laboratory Manager  
or other approved signatory

EMSL maintains liability to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. Samples received in good condition unless otherwise noted.

Samples analyzed by EMSL Analytical, Inc. Cinnaminson, NJ

Initial report from 02/01/2016 12:03:36